

# T. Mitchell Enterprises



52151 East 345 Road  
Jay, Oklahoma 74346  
Phone: 918 787-6008  
Fax: 918 787-4195  
E-mail: [ted@tmitch.com](mailto:ted@tmitch.com)

## PANTERA PARTS INTERCHANGE\*

(See Disclaimer at bottom of page)

GRP/PANTERA PART	INTERCHANGE PART NUMBER	COMMON APPLICATION	MODIFICATIONS / COMMENTS
12 Brake Master Cylinder Seals	Fiat #4115452	1968-1971 Fiat 850 sedan wheel cylinder	
12 Rear Brake Pads	D-105 Beck 082-0506  Hawk Brake #HB175  (GT5S Lucas/Girling GPG97)	Front pads for: 1964-70 Ford Cortina 1972-76 Jensen Healy	EIS catalogue lists different pads for each of the listed applications ??? So use only the interchange part number.  Hawk Brake web site is <a href="http://www.hawkbrake.com">www.hawkbrake.com</a>
12 Front Caliper Seal	Girling SP-2691		2 ea. side.
12 Rear Caliper Seal kit	Girling SP-2691  FAG KC 14000 Beck 071-1200  Peugeot #4449.15	Peugeot 504 diesel	2 ea. side.  Use 1 kit.  All parts fit except for Caliper housing (diff. bolt pattern)
12 Parking Brake Plastic Spacer	Peugeot #4408.04	Peugeot 504 diesel	
12 Parking Brake Lever		1971-73 Mercury Capri	
13 Steering Column / Ignition Assembly and housing		1971-73 Mercury Capri	
14 Rear Wheel Bearing	Outer 6308 Single row double sealed (GT5S 6309 Single row double sealed)		Obtainable from any Bearing supply. Electric motor grade has more clearance in the balls and seems to hold up better.

	Inner 6208 Single row double sealed (GT5S NU 2208 w/ National 55X80X8 seal)		
14 Front wheel seal	(GT5S National 472164)		May be good for earlier Panteras
15 Axle Shaft Universal Joints	<b>Original DeTomaso half-shafts ONLY (not Spicers).</b>	May be 70's Toyota 2WD truck driveshaft.	Powertrain Industries in SoCal (714) 255-7030 Approximately \$35.00 ea. These are a few thousandth longer than original, so be sure to specify the thinner retaining clips for a Pantera.
16 Clutch Master Cyl Kit	Beck/Arnley 071-5771 EIS #C7679	Brake M/C	Only two of the five parts in the kit fit. The rear seal on the piston; the "cup" side, must be installed facing inward, toward the fluid. The front seal is symmetrical, and can be intalled either way
16 Clutch Slave Cyl Kit	Beck/Arnley 0713438 EIS C663	1980-84 Alfa 2000 1960-63 Chev truck w/1" cyl	Use 1 kit. Discard boot (may require shortening rod to 3 inches)
16 Clutch Pilot Bearing	Ford #D8TZ 7600-A	Ford	Be sure it is the needle bearing
27 Radiator Fan Brush kit	Lucas WKB102		Board has 3 brushes. Remove center unit
32 European Front Parking lights	GT5 & GT5-S	British Austin 1100	Orange and White
32 Tail Lights		Maserati Ghibli/Bora/Indy Bricklin Late '60's Alfa Berlina 4 dr. Sedan	
33 Window Switch	GT5-S GT5-S Lighted	1984 Alfa spyder 1983 Alfa GTV6	
33 Heater Fan Switch	00605-06988	1978 Alfa Romeo Spyder	Fan symbol and chrome bezel
33 Temperature Sending Switch (block mounted)	DOZZ 10884-A TS-58	1970-up all w/ 351C 1971 Mustang w/ 351C	Ford Standard brand
35 Window/Headlight Motors		Most early '70's Maserati & Citroen	

44 Door Latch Striker	New (1988?) Fiat Cinquecento	Approximately \$10
47 Side Marker Lenses (not bezel)	1971-73 Mercury Capri	
47 Ghia Badges	1978 Ford Fiesta Ghia	

**RETROFIT/UPGRADE\***  
**(NOT DIRECT REPLACEMENT BUT MAY WORK)**

GRP/PANTERA PART	INTERCHANGE PART NUMBER	COMMON APPLICATION	MODIFICATIONS / COMMENTS
12 Front Brake Pads		1967-74 Volvo 140 w/ Girling calipers only  1975-95? Volvo 240 w/ Girling calipers only	Requires drilling new pilot hole and slight grinding for clearance (use stock for pattern).
12 Brake Master Cylinder		All Volvo 240 w/ fuel injection	Exits on same side and is 22.2 mm (7/8 in) dia. (near stock). Requires new power booster pushrod, a 2 mm spacer with some adapting of mounting bolts between booster and M/C. <b>WARNING!</b> May require adjustable proportioning valve.
12 Brake Rotors		Porsche 911  Volvo 700-900 series	.810 thick Ventillated Rotors for stock calipers. Requires fabricated "hat".  .810 thick Ventillated Rotors for stock calipers. Requires 4 mm spacer and removed the shims between the caliper and the spindle. Also Enlarging the center hole to fit the pantera hub. Redrilling bolt pattern. Rear rotor hub surface is flattened to provide a nice seating area for the bolt heads and a ridge to keep the bolts from turning.  Both covered in Jan 98 POCA Newsletter.



14 Suspension Bushings	Chrysler 2071204		Bolt hole is slightly larger, requiring drilling out holes on mounting brackets and larger bolts. Also, bushing is slightly undersized requiring shim material around bushing (metal from 1 gallon can approximately right thickness)
33 Various Rocker Switches	"GC", red and white package. #35-3695 (On)-Off-(On) Snap-In Appliance Rocker. Rating 15A 125VAC, DPDT Mounting Hole .830" x 1.450"		Available at various electronics stores. Not exact duplicate and needs some filing of the hole. Approximately \$7.99 retail.
36 A/C filter/dryer	Murray #208631  Evap Inc #4104	1984 Volvo 240  '70-'80 toyota landcruiser, '78-'79 toyota supra, '71-'79 toyota celica	Not exactly identical but a good substitute. The cylinder size is the same. The site glass is ok but the pressure relief mounts differently. May need 2 3/8-to-3/8 male insert o-ring - to - male flare, w/2 - #6 o-rings.  This may be a better match.
44 camloc fittings around the trunk boot			Aeroworks, Inc. Oakland/Pontiac Airport, Waterford, Michigan  1-(800)-356-1671 - FAX (810) 666-1390  The best thing to do is get their catalog. It's filled with neat hard to find stuff.
44 Door Striker assy.	Right, Fiat #4325900 Left, Fiat #4325901		Right side is exact replacement Left side stamping has an additional ear that must be removed and replated.(white plastic part can still be used w/ your old part). Retail \$18 each

Last Updated: Monday, June 04, 2001 19:47:35

**\*DISCLAIMER:**


This list is presented as a Public Service. References may contain obsolete data and no warantee is made as to accuracy or applicability. It is not intended to replace factory or other recommended service procedure, but is provided for information only. Ted Mitchell, Performance Enterprises, California Highway Panteras of Inland Empire, or the Pantera Owners Club of America will not be held liable for the interpretation or implementation of same, and suggests you consult your parts and/or service specialist for applications to your specific vehicle.


[BACK TO T. MITCHELL ENTERPRISES](#)

OR




[Pantera Vader Parts 4sale](#)

 [Pantera Tech Stuff](#)

 [Pantera Links](#)

 [Vader Pantera](#)

 [ActiveX animation of Vader](#)

[BACK TO SHANE INGATE'S DETOMASO PANTERA PAGE](#)

[BACK TO POCA](#)

Pantera Owners Club of America-Pantera Parts Interchange

As our Panteras age gracefully, replacement parts become increasingly rare and expensive. Pantera owners must therefore become increasingly persistent in the pursuit of affordable parts. Listed below are parts interchanges. Some are specific while some are very general. While every effort is made to provide helpful information, no guarantee is made as to the absolute accuracy of each interchange.

FURTHER INPUT FROM POCA MEMBERS IS APPRECIATED! MM

Mitch Mentor  
2162 Marine Drive  
Bremerton, WA 98312  
206-478-0161

**Part Description:**      Steering Column      **Group 13**

Ford Number:                      D16Y3514A  
DeTomaso Number:              03014A  
Interchange Part Number:      D2RY3580A  
Interchange Part Description:    1971-73 Mercury Capri

**Part Description:**      Parking Brake Lever      **Group 12**

Ford Number:                      D0RY2781A  
DeTomaso Number:              01420A  
Interchange Part Number:      D0RY2781A  
Interchange Part Description:    1971-72 Mercury Capri built before 02/01/72

**Part Description:**      Ignition Cylinder Assembly      **Group 13**

Ford Number:                      D1RY3675C  
DeTomaso Number:              03038A  
Interchange Part Number:      D1RY3575A  
Interchange Part Description:    1971-73 Mercury Capri

**Part Description:**      Ignition Housing Shroud      **Group 13**

Ford Number:                      D1RY3530-L & D0RY3530-B (left & right)  
DeTomaso Number:              03026A & 03027A  
Interchange Part Number:      N/A  
Interchange Part Description:    1971-73 Mercury Capri

**Part Description:**      Heater Fan Rocker Switch      **Group 33**

Ford Number:                      D16Y18578-A (before serial number 2292)  
DeTomaso Number:              14012A  
Interchange Part Number:      00605-06988  
Interchange Part Description:    1978 Alfa Romeo Spyder  
Switch has fan symbol and chrome bezel.



Part Description: Front Hood release Lever

Group 44

Ford Number: D16Y16914-A  
DeTomaso Number: 18106A  
Interchange Part Number: 00607-07635  
Interchange Part Description: 1978 Alfa Romeo Spyder

Part Description: Front Wheel Bearing - Inner - Cone & Roller

Group 11

Ford Number: B5A1201A  
DeTomaso Number: 01020A  
Interchange Part Number: LM67048  
Interchange Part Description: Timken Bearing  
1965-69 Mustang, 1968-69 Thunderbird, Mercury & full size Ford

Part Description: Front Wheel Bearing - Inner - Bearing Cup

Group 11

Ford Number: B5A1202A  
DeTomaso Number: 01021A  
Interchange Part Number: LM67010  
Interchange Part Description: Timken Bearing  
1965-69 Mustang, 1968-69 Thunderbird, Mercury & full size Ford

Part Description: Front Wheel Bearing - Inner - Seal

Group 11

Ford Number: D16Y1190A  
DeTomaso Number: 01022A  
Interchange Part Number: 6815  
Interchange Part Description: Timken Bearing  
1965-69 Mustang, 1968-69 Thunderbird, Mercury & full size Ford

Part Description: Front Wheel Bearing - Outer - Cone & Roller

Group 11

Ford Number: B5A1216A  
DeTomaso Number: 01017A  
Interchange Part Number: LM11949  
Interchange Part Description: Timken Bearing  
1971-78 Mercury Capri, 1965-69 Mustang (8cyl), 1968-69 Mercury

Part Description: Front Wheel Bearing - Outer - Bearing Cup

Group 11

Ford Number: B5A1217A  
DeTomaso Number: 01018A  
Interchange Part Number: 11910  
Interchange Part Description: Timken Bearing  
1971-78 Mercury Capri, 1965-69 Mustang (8cyl), 1968-69 Mercury

Part Description: Ghia Badges

Group 47

Ford Number: D16Y16604A  
DeTomaso Number: 22011A  
Interchange Part Number: D9RY16228A  
Interchange Part Description: 1978 Fiesta.Ghia. Badges are plastic.  
Ford Scorpio Germany #6060935.

Part Description: Key Set

Group 44

Ford Number: D16Y6322053A/Rnd Handle D16Y6322053B/Rec Handle  
DeTomaso Number: 18132A  
Interchange Part Number:  
Interchange Part Description: Fiat 126/127

Part Description: Rear Deck Lid Lock

Group 44

Ford Number: D16Y6343625A  
DeTomaso Number: 18130A  
Interchange Part Number:  
Interchange Part Description: Fiat Dino or Montreal.

Part Description: Headlight Assembly - European Round

Group 32

Ford Number: D16Y13099A(B)prior serial#2729 D26Y13099A(B) aft. serial#2729  
DeTomaso Number: 16006A  
Interchange Part Number: N/A  
Interchange Part Description: Volvo 240.

Part Description: Heater Valve Assembly

Group 36

Description: Heater Valve

Ford Number: D36Y18495A  
DeTomaso Number: 12007A  
Interchange Part Number: 18495A-A  
Interchange Part Description: Ford. Probably from a Corinta or other European Ford.  
Out of production according to Ford. Need to adapt slide cable.

Part Description:

Ford Number:  
DeTomaso Number:  
Interchange Part Number:  
Interchange Part Description:

Part Description:

Ford Number:  
DeTomaso Number:  
Interchange Part Number:  
Interchange Part Description:

Part Description:

Ford Number:  
DeTomaso Number:  
Interchange Part Number:  
Interchange Part Description: